

The STIHL logo is displayed in white, italicized, sans-serif capital letters on a solid orange rectangular background.

RECALL

STIHL recalls a limited production range of mist blowers STIHL SR 430 / STIHL SR 450



STIHL has learned that a limited number of STIHL mist blowers have cracked flywheels. A failure during the life time of the machine would pose a projectile hazard to the user or a bystander. As a responsible manufacturer, STIHL has decided to recall and repair the mentioned mist blowers.

Only trained people can detect a damaged flywheel.

Affected serial number range: 369259472 up to and including 370391433

If you have purchased a mist blower SR 430, or SR 450 in the year 2020 or 2021 and it is in the given serial number range, please **discontinue using the machine immediately!**

Please contact your local STIHL dealer for a flywheel replacement. This repair is free of charge to you.

We ask for your understanding in this precautionary measure. Please take this action in the interest of your own safety and that of third parties.

If you have any questions please do not hesitate to contact us.

To be displayed until: 30-Jun-2022